

Orbit Newsletter Digital Publication

Q2 2022

Gas Piping Condition Monitoring deployment

Abstract

This case describes structural tests performed on the gas pipe and piping supporting system installed along a bridge. These tests were part of an investigation that was done as a preparation for the monitoring system installation. The objective was to obtain the information regarding the vibrational responses, the natural frequencies, and the related modal shapes, to optimize the distribution of permanent sensors. These sensors will form part of the condition monitoring system – to be installed in the immediate future – which will allow early detection of system degradation and overall prevent catastrophic failure.

Access to the requires structural areas was challenging and required utilization of two different cranes have been used with the support of third-party manpower to be able to optimize the roving accelerometer methodology.

The experimental modal parameters (natural frequencies, modal damping, and mode shapes) of the piping have been extracted from the data measured. As preliminarily planned, the test allowed BN to understand the expected positions to be used for the permanently installed sensor which is the part of the condition monitoring system.

Introduction

Bently Nevada (BN) Machinery Diagnostic Services (further referred as MDS) has been invited to evaluate the possibility of monitoring the intensity of induced vibration on the gas piping mounted under a road traffic bridge. In fact, the main scope is to evaluate, via the amplitude level, the risks connected to the structural integrity of the system, strictly connected to the possible condition degradation of the bridge (and in general of the structures where the piping is anchored) which can lead to interruption of the continuity of gas delivery. The objective is obtaining the information regarding the vibrational responses, the natural frequencies, and the related modal shapes, in order to optimize the distribution of permanent sensors which will be form the condition monitoring system to be installed in the immediate future. It has to be noted that Italgas does not own the bridges, but their piping structures are strongly dependent from bridges stabilities.

It has also been highlighted that in 2018, during a rainstorm on 14 August, a 210-metre section of ponte Morandi viaduct collapsed and tragically 43 people died.

After extensive analysis of the structural failure were executed, the collapse raised concerns about the general condition of infrastructure in Europe, with studies in Italy, France, and Germany suggesting that a significant number of bridges are in need of renovation or replacement due to corrosion and structural deterioration.



Figure 1: Machine train diagram for Case 1

Definition, Preliminary Testing and Data Collection Initiation

Historical Background

Since no previous tests were reported on this structure and no theoretical calculation were ever executed, it was not possible to anticipate the expected piping response.

Therefore, before the test, a thorough assessment of methodology plus a site survey had to be executed, in order to prevent any possible difficulties that could have been encountered during data acquisition.

Finally, before mobilizing to site, the following possible solutions were drafted:

- Solution 1 for test: Full structural test to be executed measured eventually with and without cars (to have better understanding about excitation).
- Solution 2 for test: Motion amplification (MA) camera to do a preliminary test. Subsequently we will perform a structural test but with targeted amount of points (as suggested by motion amplification results).

Survey

Due to the non-standard request, the MDS Engineer had to think out of "his comfort zone" and the survey was scheduled with the aim of answering to the following questions:

- Is there enough measurable excitation (therefore not sure response from the motion amplification camera)?
- Can the MA camera be positioned easily in order to obtain a good resolution (in theory tilting and excessive distance to be avoided)?
- How easily can the Piping be accessed (appears not easily from either the top or the bottom)?
- How many people needed to complete the scope?
- Can Traffic be stopped?
- Is the piping suitable for Magnet transducer mounting??
- Etc., etc...



Fig 2: View from north side of the bridge from the bottom



Fig 3: View of obstacles present on the south side of the bridge



Fig 4: Overall view of the bridge (north on the left side of the picture)



Fig 5: Example of temporary magnet based installation of the sensor

And after a thorough survey and a detailed discussion, the final solution decided was:

- Full Modal analysis.
- 2 cranes needed with subcontractors (1 for the hammer and 1 for the triax sensor).
- MDS to supervise the activity from the bridge and using the BN Scout140 Portable Vibration Analyzer & Data Collector.
- Magnet base to be used for the sensor.
- 4 BNC-BNC cables 100m long needed.
- 1 week planned (considering the need of reposition the cranes, 4 averages needed for every point and eventual need of retaking few points after preliminary analysis).

Therefore, all the premises were suggesting that nothing could go wrong.

Unfortunately, the majority of us knows very well the following rule:

And, even if we know that theoretically this “law” is not always applicable, during the execution of the test there were several practical demonstration of this rule.




Fig 6: Murphy's law

Test Execution:

Murphy's law - Practical demonstration 1:

- Expectations: Meeting thoroughly planned with third party contractor at 7am on the bridge
- Reality: At 12:00 still nobody from third party contractor was there, because, due to an issue with the crane rental. They arrived with about 5 hours of delay.

Murphy's law - Practical demonstration 2:

- Expectations: BN required 2 cranes to easily access the piping under the bridge to allow efficient Modal data collection - “roving” of the sensor along the required locations, while exciting (hitting) another location on the bridge.
- Reality: Third party contractor brings 1 crane.
- Ok, so maybe that's still enough....
- Not too fast: The crane wasn't tested on the bridge and it couldn't reach the piping!



Fig 7: Bridge view at 12:00 of first day



Fig 8: Picture of the wrong crane installed on the bridge

Murphy's law - Practical demonstration 3:

- Expectations: Finally, during the second day, the correct crane attended site. Unfortunately only 1 crane rather than 2 but perhaps an increased speed from the MDS Engineer in the data acquisition process could have allowed to still finalize it on time!
- Reality: At 10:00 of second day there was heavy rain (Fig 9) and, in accordance, this generated a "not so sunny" response from the MDS Engineer's face (Fig 10).



Fig 9: Heavy rain condition on the bridge



Fig 10: Unhappy MDS under the rainy data collection

Murphy's law - Practical demonstration 4:

- Expectations: Data collected without any criticality till early afternoon
- Reality: At 16:00 the data began indicating some noise, and, after a loop check, there was the evidence of the triaxial cable being broken

However, it was apparent that the axial vibration was not the main contributor to vibration.

As the activities were adequately planned the MDS Engineer utilized the backup single axis sensors to continue data collection. In addition the second crane was now present, thus the activity accelerated dramatically and the test was still finalized on time and the third day.



Fig 11: Broken cable



Fig 12: Monoaxial sensors positioning



Fig 13: 2 Cranes setup

Structural Test Results:

Here below are indicated the modal parameters extracted by the post-processing of the experimental modal measurements. The post processing was performed with ME'scope (Vibrant Technology) software. The natural frequency found with automatic interpolation in the range from 0 to 500 Hz is indicated in the pictures below. For the mentioned natural frequency, it was also indicated the corresponding modal damping, in terms of percent of the critical damping:

Frequency (or Time)	Units	Damping (%)
490	Hz	0.269

Fig 14: Global interpolation – natural frequency result




Fig 15: Global interpolation

The sources of excitation on the bridge and/or directly on the piping are not fully known and repeatable, these are mainly due to car/truck passing on the bridge and other phenomenon like earthquakes. These sources were expected to typically excite the low frequency range therefore, there was no clear need to extend the frequency range over 500Hz.

Of course, with the source of excitation not being definitive, no segregation margin can be calculated between excitations and natural frequency. Other possible modes, in the lower frequency range were not apparent either due to a lack of excitation force from the impact hammer or were highly damped, so that no clear response can be seen while making an overall interpolation of the piping response. Therefore, some local interpolations were executed as shown in Fig 16 to Fig 19:

Modal Parameters		
Select Mode	Frequency Hz	Damping (%)
1	87.4	0.179
2	112	0.418
3	115	0.344
4	137	0.587
5	149	0.675

Fig 16: Local interpolation (0-158Hz) – natural frequency result




Fig 17: Local interpolation (0-158Hz)

Modal Parameters		
Select Mode	Frequency Hz	Damping (%)
1	87.4	0.179
2	112	0.418
3	115	0.344
4	137	0.587
5	149	0.675

Fig 18: Local interpolation (158-315 Hz) – natural frequency result




Fig 19: Local interpolation (158-315 Hz)

Fig 20 shows a mode shape, associated to one of the abovementioned natural frequencies, obtained by the overall interpolation.

Through comparison of all the mode shapes obtained from each natural frequency, a clear distribution of permanent probes installation was defined. Utilizing this approach would avoid sensors being positioned on nodal points which, from their definition, do not have a response for the related mode - thus no valid information would be retrieved with sensors positioned in those locations.




Fig 20: Mode shape related to the mode at 87.4Hz

An example of detailed instruction for the sensor installation is outlined in Fig 21 and a total of 12 sensors were planned to be installed on the piping:

- Sensor N°1: on the point 9 (around 2.5m after the 2nd bracket) mounted vertically from the top.
- The direction has been chosen also taking into account the ease and the integrity of installation considering the sensors too much exposed to atmospheric environment if oriented in horizontal direction.




Fig 21: Example of sensors 1 location plan

To provide effective condition monitoring and overall minimize capital expenditure, the BN System1 Evo monitoring and diagnostic platform was deployed through the „Bently Connect“ hosted solution (Fig 24). On site probes were wired to VB Online Pro, which is providing vibration data via secured Internet connection to the BN Remote Monitoring Center (RMC). All data is stored in the hosted environment and access for analysis remotely.



Fig 22 Example of sensors installed



Fig 23: VB Online Pro monitoring system installation




Fig 24: Bently Connect architecture

Subsequent to the system setup and to the data collection initiation, the first month of data has been acquired.

Based on the data collected, some spectral bands have been configured, in order optimize the monitoring and develop further understanding of the variation in the normal condition of the piping.

From first principles the natural frequency is given by: $\sqrt{K/M}$, where K is the system stiffness and M its mass. A change in the stiffness - due to the loosening of a structure or to fatigue being weakening the material and possibly damaging the system) - would change its natural frequency. A change in the excitation - which at the moment, as already stated, is unknown - could increase or decrease the response of the system, exciting with different amplitude its natural frequencies.

Following an example taken directly from System 1 configuration:

General		Data Collection		Measurements						
Points		Spectrums & Waveforms		Trended Variables		Setpoints				
Machine Name	Name	Module	Channel	Channel Type	Measurement	Active	Integrated	Band Lower...	Band Upper...	Top Scale
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	Bias	<input checked="" type="checkbox"/>	-	-	-	-24.0 V
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	2 Hz - 2000 Hz	<input checked="" type="checkbox"/>	-	2.0 Hz	2,000 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	0/84Hz	<input checked="" type="checkbox"/>	-	0.0 Hz	84.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	1^ Critical	<input checked="" type="checkbox"/>	-	85.0 Hz	89.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	90/109Hz	<input checked="" type="checkbox"/>	-	90.0 Hz	109.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	2^/3^ Critical	<input checked="" type="checkbox"/>	-	110.0 Hz	117.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	118/134Hz	<input checked="" type="checkbox"/>	-	118.0 Hz	134.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	4^ Critical	<input checked="" type="checkbox"/>	-	135.0 Hz	139.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	140/146Hz	<input checked="" type="checkbox"/>	-	140.0 Hz	146.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	5^ Critical	<input checked="" type="checkbox"/>	-	147.0 Hz	151.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	152/202Hz	<input checked="" type="checkbox"/>	-	152.0 Hz	202.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	6^ Critical	<input checked="" type="checkbox"/>	-	203.0 Hz	207.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	208/214Hz	<input checked="" type="checkbox"/>	-	208.0 Hz	214.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	7^ Critical	<input checked="" type="checkbox"/>	-	215.0 Hz	219.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	220/264Hz	<input checked="" type="checkbox"/>	-	220.0 Hz	262.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	8^ Critical	<input checked="" type="checkbox"/>	-	263.0 Hz	267.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	268/486 Hz	<input checked="" type="checkbox"/>	-	268.0 Hz	486.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	9^ Critical	<input checked="" type="checkbox"/>	-	487.0 Hz	493.0 Hz	2.0 in/s rms
Gas Piping Villa Potenza	Accel-1 (Point 9)	1	1	Acceleration Channel	494/2000Hz	<input checked="" type="checkbox"/>	-	494.0 Hz	2,000 Hz	2.0 in/s rms

Fig 25: Spectral bands configuration for the channel 1

After having created the frequency bands, some Statistical Alarms (for each spectral band) have been calculated using the average and the standard deviation for the following parameters:

- Overall vibration level (global vibration amplitude measured by each sensor) to capture the overall health level of the system.
- Natural frequencies spectral band vibration level, in order to capture the increase of system response (increase of excitation or decrease of damping).
- “Out of band” vibration level, in order to capture the possible shift of natural frequencies (because of change in stiffness conditions).

Machine Name	Name	Measurement	Alarm Source	Alarm Type	State	Level 4... Under	Level 4... Over	Level 4... Under	Level 4... Over	Level 3... Under	Level 3... Over	Level 3... Under	Level 3... Over	Level 2... Under	Level 2... Over
Gas Piping Villa Potenza	Accel-1 (Point 9)	Bias	Condition Monitoring	Out of Band	Standard	<input type="checkbox"/>	<input checked="" type="checkbox"/>	-14.52 V							
Gas Piping Villa Potenza	Accel-1 (Point 9)	2 Hz - 2000 Hz	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.085 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	0/84Hz	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.085 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	1^ Critical	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	90/109Hz	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	2^/3^ Critical	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	118/134Hz	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	4^ Critical	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	140/146Hz	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	5^ Critical	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	152/202Hz	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	6^ Critical	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	208/214Hz	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	7^ Critical	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	220/264Hz	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	8^ Critical	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	268/486 Hz	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	9^ Critical	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						
Gas Piping Villa Potenza	Accel-1 (Point 9)	494/2000Hz	Condition Monitoring	Over	Standard	<input type="checkbox"/>	0.0 in/s rms	<input checked="" type="checkbox"/>	0.01 in/s rms						

Fig 26: Spectral band alarms for the channel 1

First Monthly Analysis

After the implementation phase, the vibration data from the first month of activity was analyzed in System1 (few examples in Fig 27 and 28) and the following consideration can be drawn:

- No critical frequency seems to be excited at the moment, neither in normal condition nor in exceptional vibration events.
- The behavior of the probes is repeatable (under the aspect of frequency components) and also as daily evolution of overall amplitude, verifying the health of the monitoring system.
- As expected, the sensors installed closer to the brackets are showing a lower overall amplitude.
- The excitation frequencies seem to be mainly 2.5Hz, between 12.5 and 15Hz, between 22.5 and 25Hz and finally between 45 and 50Hz.
- During vibrational events, the amplitude seems to be increasing in correspondence to these known frequencies and no different spectral pattern could be seen.
- There is currently undergoing a study aimed to correlate vibration content with the excitation sources. Those, in particular, are expected to be mainly related to the bridge characteristics and/or also due to car/truck passages on the bridge, but also other random excitation sources like weather and animals




Fig. 27: Zoom between 0 and 500Hz of the current spectrums of velocity signal for the probes 1 and 2




Fig. 28: Zoom between 0 and 500Hz of the current Waterfall spectrums of velocity signal for the probes 1 and 2

Conclusion

- This is the first application of this type in Italy.
- if, at the end of the testing phase, the application demonstrates value, the customer is considering extending the application to other bridges supporting gas pipes within its distribution grid (for a significant achievement and future scope for BN).
- BN MDS demonstrated their advanced vibration and condition monitoring capabilities outside of their “traditional” field of turbomachinery rotor dynamic analysis, , delivering as always a best in class solution for the customer.
- A good planning and a flexible mindset can allow us to overcome any unforeseen challenges during the execution of our work.

Nicolas Péton Ph.D.

Nicolas joined GE in 2006 in the Machinery Diagnostic Services group where he was MDS Technical Leader for South and West Europe. Nicolas has a PhD. Degree. Previously he worked for two different manufacturers (steam turbine, expander/compressor) where he was in charge on site of the startup activities worldwide. He also worked as an operation and maintenance engineer in the chemical industry and as a mechanical/acoustical research engineer in research institutes.

Sergey Drygin, Ph.D.

Sergey joined GE in 2006 in the Machinery Diagnostic Services group and has 19 years of experience in condition monitoring and machinery diagnostics on various types of industrial machinery as Senior Machinery Diagnostics Engineer. Sergey has a PhD. degree in Machinery and Technology, Engineer's and bachelor's degrees from Faculty of Electro-mechanical Engineering, at Kuzbass State Technical University, Russia. Sergey is certified trainer for Bently Nevada products, more when 14 years he is CAT III certified expert from ISO Mobius and Russian Society of NDT Certification.

Pierfrancesco Guagnano

Pierfrancesco, currently Global Program Manager inside Bently Nevada organization comes from a background as a SSA Site Lead for South Europe where he led the execution and growth of our service agreements. He joined originally Bently Nevada in 2016 as a Machinery Diagnostic Engineer, gaining significant experience in the condition monitoring and machinery diagnostics on various types of industrial machinery. Previously had roles of increasing responsibility in the design engineering and maintenance engineering in the Power Generation and Oil & Gas Industries. He has a Master's Degree in Energy Engineering awarded by the “Università di Pisa” and is an ISO Cat II Vibration Analyst.



Nicolas Péton Ph.D.

Global Technical Leader
Global Director – MDS services
Bently Nevada, a Baker Hughes company
Nantes, France

E nicolas.peton@bakerhughes.com



Sergey Drygin, Ph.D.

MDS Technical Leader – Russia and CIS,
Turkey region
Bently Nevada, a Baker Hughes company
Moscow, Russia.

E sergey.drygin@bakerhughes.com



Pierfrancesco Guagnano

Global Program Manager
Bently Nevada, a Baker Hughes company
Italy

E pierfrancesco.guagnano@bakerhughes.com