

EZReam solves customer's casing running challenges

CHALLENGES

- 12 1/4-in. intermediate section through the Clear Fork formation
- Wellbore stability issues
- Multiple stuck casing incidents
- Costly remedial operations to cleanout wellbore

SOLUTION

- 11 1/2-in. [EZReam™](#) deployed on 9 5/8-in. casing
- Carbide cutters for active reaming through tight spots
- 360° spiral gauge for increased stability and reaming efficiency with or without casing rotation
- PDC drillable, concave profile reduces total drill-out time

RESULTS

20 casing runs

Consecutive runs to TD with no issues

Zero drill-out issues

No impact to subsequent section performance